Figure 1 - Geographic Location of Gas and Scrub Well, Bingham County PWS Number: 6060009